

Empty Cylinder Return Checklist

1. Preparing Cylinders for Return

- Returning a minimum of 8 empty 125 lb cylinders or 1 empty half-ton/ton cylinder (required for Freight Collect). Empty and Return for Inspection (e.g., defectives) cylinders can be palletized together.

Common Cylinder Empty (Tare) Weights

- 125 lb: 55 lb
 - Half-ton: 370 lb
 - Ton: 1,160 lb
- Cylinders are properly palletized and banded (refer to “How to Return Your Chemours Cylinder” poster).
 - Shipment is at least 75% Chemours-owned cylinders.

Chemours Cylinders	Non-Chemours Cylinders			Cylinder Manufacturers (No Ownership Mark)
DuPont	Allied	Forex	Pennsalt	Manchester
KC	Arkema	Genetron	Pennwalt	Worthington
KC INC	Atolina	Honeywell	PSMCO	
UKON	Elf Atochem	Isotron	Racon	
YUKON	Forane	National	United	

2. Submitting Cylinder Return Request

- Completed online Bill of Lading (BOL) at <http://chemours-site.force.com/BOL>
- Included pick up hours and best contact name on BOL to ensure smooth return process.

3. Preparing Cylinders for Shipment

- Attach copy of BOL to shipment as a packing list.
- BOL given to carrier at pickup.
- Return Authorization (RA) number has been written on all cylinder tags.
- Provide appropriate placards to the driver upon request:
 - For shipments with gross weights over 1,000 lb: A green, nonflammable Class 2 placard is required.
 - For ton cylinders or shipments with gross weight over 8,820 lb of a single hazmat material (having the same proper and identification number): An UN-specific green, nonflammable Class 2 placard is required.
 - Placards can be purchased online at various sites, e.g., www.labelmaster.com

